VENSTAR®

VENSTAR

Master Calibration Procedure Guide

ColorTouch Thermostats

1) Press the MENU button
2) Press the DOWN arrow key
3) Press the SETTINGS button
4) Press the INSTALLATION SETTINGS button
5) Press the DOWN arrow key repeatedly to reveal the SENSOR SETTINGS button
5) Press the SENSOR SETTINGS button
6) Press the CALIBRATE SENSORS button
7) Press the THERMOSTAT button
8) Use the UP or DOWN arrow keys to calibrate the sensor +/- 7°F
9) Press the HOME button to return to normal operation

Models: T5800, T5900, T6800, T6900, T7800, T7850, T7900, T8800, T8850, T8900

Slimline Thermostats

1) Press and <u>hold</u> the MODE button
2) While holding MODE, press and <u>hold</u> the FAN until all the icons appear on the display
3) Press the UP <u>and</u> DOWN arrow keys at the same time, <u>twice</u>
4) Press the UP or DOWN arrow keys to calibrate the sensor +/- 3°F
5) Press the MODE button one or more times to return to normal operation

Models: T1700, T1800, T1900, T2700, T2800, T2900

Wireless Thermostat

1) Press and hold the MODE button
2) While holding MODE, press and hold the DOWN arrow key until all the icons appear on the display
3) Press the MODE button twice
4) Press the UP or DOWN arrow keys to calibrate the sensor +/- 3°F
5) Press the MODE button once to return to normal operation

Model: T1100RF / T1100REC

Programmable Value Thermostats

1) Slide the PROGRAM switch to the SET position
2) Press and hold the NEXT button until the deadband adjustment screen appears
3) Press the NEXT button once
4) Press and hold the NEXT button until all of the icons appear
5) Press the NEXT button once
6) Press the UP or DOWN arrow keys to calibrate the sensor +/- 3°F
7) Press the NEXT button once
8) Slide the PROGRAM switch to the RUN or OFF position to return to normal operation

Models: T1035 and T1045

Super-T2 and FlatStats

1) Press and <u>hold</u> the MODE button
2) While holding MODE, press and <u>hold</u> the DOWN arrow key until all the icons appear on the display
3) Press the MODE button once
4) Press the UP or DOWN arrow keys to calibrate the sensor +/- 3°F
5) Press the MODE button once to return to normal operation

Models: T1010, T1050, T1075, T1070, T1000FS, T1100FS