

SOURCE 1
Unitary Products
Johnson Controls Inc.
8909 E 35th Street North
Wichita, KS 67226
(316) 260-2900



PARTS INFORMATION

DATE: May 6, 2013

YP-018-13

TO: All Source 1 Customers

SUBJECT: TPLC Furnace ECM Motor Replacement

Please be advised that AO Smith ECM motors are no longer available from our supplier for these furnaces models. Once Source 1 inventory is exhausted, we will switch to a Regal Beloit 2.3 motor as our replacement offering.

This motor change requires changing two harnesses. Please order harness **S1-02541460000** (ECM Power Harness) and S1-02541349000 (ECM Control Harness) in addition to ordering any of the following motors when converting from an AO Smith to a Regal Beloit motor.

We will also be linking this YP letter to these motors in UPGNET and adding the harness part numbers as related items in SMARTSEARCH.

Model	Old AO Smith Motor	New Regal Beloit Motor
TPLC060A12MP12C	S1-02436006000	S1-02435787000
TPLC080B12MP12C	S1-02436006000	S1-02435788000
TPLC080C16MP12C	S1-02436007000	S1-02435789000
TPLC100C16MP12C	S1-02436007000	S1-02435790000
TPLC100C20MP12C	S1-02436008000	S1-02435791000
TPLC120C20MP12C	S1-02436008000	S1-02435792000

Thank you,

Henry Boss
Residential Parts Manager
Source 1™ HVAC Service Parts